

DECLARATION OF CONFORMITY

according to EN ISO/IEC 17050-1:2010

Dell Inc.Phone512.338.4400Dell Products Europe BVOne Dell WayFax512.283.9264Raheen Business ParkMS: PS4-30Webwww.dell.comLimerick, IrelandRound Rock, Texas USA 78682www.dell.com/regulatory complianceEmail regulatory compliance	Manufacturer's Name and Address:			EU Authorised Representativ
MS: PS4-30 Web <u>www.dell.com</u> Limerick, Ireland	Dell Inc.	Phone	512.338.4400	Dell Products Europe BV
	One Dell Way	Fax	512.283.9264	Raheen Business Park
Round Rock, Texas USA 78682 www.dell.com/regulatory_compliance Email regulatory_complia	MS: PS4-30	Web	www.dell.com	Limerick, Ireland
	Round Rock, Texas USA 78682		www.dell.com/regulatory_compliance	Email <u>regulatory_complia</u>

TYPE OF EQUIPMENT: Ethernet Switch **REGULATORY MODEL:** PowerConnect 5524 **REGULATORY TYPE:** TRADE/BRAND NAME: DELL

ive ance@dell.com

Year CE marking was first affixed to declared product

Dell Inc., as the responsible party for regulatory compliance, declares under our sole responsibility that as delivered the described product is in conformity with the Low Voltage Directive 2006/95/EC, EMC Directive 2004/108/EC, EU RoHS Directive 2011/65/EU and carries the CE-marking.

The described product has been assessed and determined compliant with the following standards:

EN 60950-1:2006 +A1:2010 +A11:2009 +A12:2011/IEC 60950-1:2005 ed2 +A1:2009 SAFETY: EN 62311:2008

- EN 55022:2010/CISPR 22:2008 EMC: EN 55024:2010/CISPR 24:2010 EN 61000-3-2:2006 +A1:2009 +A2:2009/IEC 61000-3-2:2005 +A1:2008 +A2:2009 EN 61000-3-3:2008/IEC 61000-3-3:2008
- RoHS: EN 50581:2012

SUPPLEMENTARY INFORMATION: This product has been tested and found to comply with the electromagnetic compatibility (EMC) limits for a Class A digital device pursuant to the listed directives, regulations and standards. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial/business non-residential environment. Operation of this equipment in a residential area is likely to cause harmful interference, in which case you will be required to correct the interference at your own expense. The equipment was tested in a typical configuration.

Round Rock, Texas, USA

Place of Issue

Jan. 14, 2013

Date of Issue

Signature

Maurice Wu

Full Printed Name

CDPowerConnect 5524

Dell Document Control Tracking Number

Sr. Manager, Dell Regulatory Compliance Engineering

Position/Title